

BRASS SURFACES

CARE INSTRUCTIONS

BRASS MUST BE ROUTINELY MAINTAINED TO RETAIN THE DESIRED APPEARANCE. THE DARKENING OR BLACK SPOTTING ON THE BRASS SURFACE IS SIMPLY OXIDATION TAKING PLACE. IF LEFT UNTREATED, BRASS WILL EVENTUALLY TURN ENTIRELY DARK. THE DARK OXIDIZED STATE IS THE NATURAL COLOR OF ALL COPPER ALLOYS.

MAINTENANCE AND CARE

WE RECOMMEND THAT YOU USE REGULARLY POLISH THE BRASS SURFACES IN ORDER TO STOP THE BRASS FROM TARNISHING OR TURNING DARK. BRASS METAL POLISH HELPS KEEP THE METALS SHINY AS WELL AS CLEANING OFF THE TARNISH. BEFORE APPLYING THE BRASS POLISH, YOU SHOULD WASH THE OBJECT IN WARM, SOAPHY WATER, THEN RINSE AND LET IT DRY WELL. POLISH THE BRASS SURFACE WITH A SOFT SPONGE OR CLOTH ACCORDING TO THE SPECIFIC INSTRUCTIONS ON THE BRASS POLISH BOTTLE. REMEMBER TO WASH AWAY ALL POLISH AND LET IT DRY.

CAUTION

RUB OR WASH AWAY ALL THE BRASS POLISH. IF THERE IS POLISH LEFT ON THE OBJECT, IT CAN CAUSE THE OBJECT TO TARNISH AGAIN QUICKER.

WOUND